BLUE LINE INDICATES SUGGESTED ALTERATION TO REDLINE BOUNDARY

CROSSING AS PER CYCLE DESIGN MANUAL TL607 'TOUCAN CROSSING'

Boundary 6

26, Removed during road widening

Boundary 7

Boundary 8

Boundary 9

Boundary 1

Boundary 2

Boundary 3

Boundary 4

Boundary 5

2254.05

0 10 50m

Enviroguide CONSULTING

ADDRESS:
3d Core C, Block 71, The Plaza, Park West, Dublin 12, D12 F9TN.

EMAIL:
info@enviroguide.ie

PHONE:
+353 (01) 5654730

WEBSITE:
www.enviroguide.ie

Registered Landscape Architect

LEGEND:

LEGEND

Root Protection Area

Tree Canopy

Tree Stem & Category Colour

T1-C2

Tree Number & Category

Category A Trees (high value)

Category B Trees (moderate value)

Category C Trees (low value)

Category U Trees (unsuitable for retention)

Existing hedge line

Tree to be removed to facilitate development

Hatched brown exclusion area from construction activities / compounds /site office(s)/plant, equipment and material storage. Any excavations by hand and under supervision. See Tree report for guidance.

Proposed protection fence

CLIENT:
Zolbury Limited

LOCATION:
Blackglen Road and Woodside Road, Sandyford, Dublin 18

DEPARTMENT:
Landscape

DRAWING TITLE:
Tree Protection Plan

DRAWING STATUS:
Planning

DRAWN BY: DH

CHECKED: RH

DRAWING NO: P-01

DATE: 10/12/2024

SCALE: 1-500 @ A1

Copyright for all drawings and documents prepared by Enviroguide Consulting shall remain the property of Enviroguide Consulting. Figured dimensions ONLY to be taken from this drawing. All scaled measurements are dependant on accuracy of original source. Enviroguide Consulting does not accept responsibility for 3rd party additions to this drawing.